






SET 1. Step-in development pictures of a hidden leakage event.



SET 2. Step-in development pictures of a hidden leakage event.




Evaluations

SET 3. Step-in development pictures of a hidden leakage event.



**Load bearing twin LVL
garage header support**



Evaluations

SET 4. Step-in development pictures of a hidden leakage event.

**Estimate of damage
wood rot depth: 3"**

**Estimate of damage
wood rot depth: 2"**

**No
further
invasives**



Architectural key stone left out. It was determined as the main factor causing the leakage event.



<----- Indications that internal leakage is still occurring.



<----- Resolve ----->

SET 5. Step-in development pictures resolving and repairing the leakage event.

